Approved For Release 2002/10/31 : CIA-RDP89B00980R000200480088-8 ENGINEERING STUDY 1 120 LOCKHEED AIRCRAFT CORPORATION CHANGE PROPOSAL DATE X **WSPO** X **PROJECT** AFFECTS: 1-10-62 PART NO. & MODEL OR TYPE PART OR LOWEST SUBASSEMBLY NAME OF MAJOR COMPONENT QUICK DISCONNECT HYDRAULIC SYSTEM TITLE OF PROPOSAL : GROUND TEST QUICK DISCONNECT - HYDRAULIC SYSTEM NATURE OF PROPOSAL: SEE PAGE 2 **REASON FOR PROPOSAL:** SEE PAGE 2 ESTIMATED COST AND TIME INVOLVED : ES ADDITIONAL FUNDING REQUIRED: SEE PAGE 3 ESTIMATED COST FOR KITS OR PARTS: CP NONE (SP-1922) ADDITIONAL FUNDING REQUIRED: ITEMS AFFECTED BY PROPOSAL: MAINTE-NANCE MANUAL SERVICE FLIGHT MANUAL INTER-CHANGE-WEIGHT OR WEIGHT & BALANCE TOOLS & SUPPORT EQUIPMENT MAINTE-NANCE PROCEDURE OPERATING PERFORM-ANCE MISSION SAFETY EFFEC-TIVENESS ABILITY X X EST. MAN/HRS. REQ'D. TO ACCOMPLISH CHANGE IN FIELD WEEKS AFTER APPROVAL SOURCE OF PARTS FOR KIT AVAILABILITY \_\_\_\_Q LAC DISPOSITION OF SPARES AFFECTED \$TAT Approved For Release 2002/10/31 : CIA-RDP89B00980R000200180088-8 INITIATED BY

PROJEC

Er PAGE 1 OF 3

## NATURE OF PROPOSAL

- 1. Install two self-sealing hydraulic quick disconnect fittings for connecting the hydraulic gig for ground checkout of the aircraft hydraulic system. One fitting will be plumbed to the aircrafts high pressure filter with a check valve to preclude flow to the engine driven pump connection. The second fitting will be plumbed from the hydraulic system return line upstream of the return line filter.
- 2. An access door will be provided on the right side of the fuselage at approximately F.S. 395 below the wing fillet.
- 3. Prepare and issue a Service Bulletin and fabricate the necessary kits.

## REASON FOR PROPOSAL

The present procedure for hydraulic system checkout with test stand (T.M.O.M.-2-5, Par. A. 3-109) necessitates disconnecting the suction and pressure hoses at the engine-driven pump and reconnecting these to hoses from the hydraulic gig. After the ckeckout, the pump is reconnected. Oil is lost during both steps necessitating refilling and rebleeding the system causing time delay. These new quick disconnects will eliminate this loss of oil and time.